Expert Answers to your Tech Questions Mail: Excellence Magazine 42 Digital Dr. Novato, CA 94949 Fax: (415) 382-0587 Email: excellence@rossperiodicals.com

Cone-Hugging Cayman

A friend recently introduced me to PCA autocrossing, and I have to say I'm hooked! It's such a concentrated rush, with so many turns coming at you in such a short time. I love that I can explore my Cayman's limits in a safe, controlled environment, with the only battle scars at day's end being a cone scuff or two (I found they wipe off easily with bug & tar remover). We may only be hitting 50 mph in sections, but with the "cockpit workload" it feels much faster! I feel I drove respectably at my first event with a box-stock car, finishing ahead of some Boxsters and 944s, but a ride with an instructor was an eye-opener...he had the car perfectly sliding and dancing

around the cones. Other than practice, practice, practice, do you have any tips for this autocross newbie to turn some faster times?

Congratulations on discovering the most cost-effective form of motorsport ever conceived, not to mention a real test of precision car control. You've taken the most important step already by entering and driving in an event, and pairing up with an instructor to go over the fundamentals. One of the best speed secrets is to show up early and walk the course, as many times as possible, preferably on a novice course walk with an instructor. It may be intimidating to try and memorize the entire layout at first, so make mental notes of two or three key "pinch points" on the course, which are tight slaloms or turnarounds that follow a faster section. The better you know the course, the less indecision you'll have and the faster and more aggressive you can be. As for the driving itself, the best

piece of advice we've heard is also the title of John Buffum's book on rallying: "In like a lamb, out like a lion." Those new to autocross usually overdrive the slow corners and are too timid through the fast ones, where just the opposite is required. Charging hard and overshooting a slow 180degree turn will kill a lap time, and seconds seem like hours as you're waiting for those front tires to regain bite. If you've done any road racing, forget about all that late-apex stuff for the really tight turns...get the car slowed to the point where you have front traction, hug the inside of the turn, and pick up the throttle aggressively on exit, but not too quickly because that will cause the understeer that you've worked so hard to avoid earlier in the turn. Tip No. 3? Look ahead, and keep your head on a swivel. It's uncanny how any vehicle has a tendency to go where we're looking, and fixating on a cone or piece of track only 50 feet ahead of

continued on page 28

Factory trained expert repair and restoration of all Porsche instruments.



PEEDOMETER INC.

718 Emerson St., Palo Alto CA 94301-2410 Tel: 650.323.0243 ◆ Fax: 650.323.4632



Sunset Porsche SunsetPorsche.com

Beaverton, Oregon

Genuine Factory Porsche Parts EXCELLENT PRICES



Rear Lid Shocks Fits: Cavenne 2003-2010

Rear Lid Shock | 955-512-550-06 List \$89.02

Sunset \$63.99

Glass Door Shock | 955-512-528-00 List \$23.36 Sunset \$16.79

Front Lower Control Arm

Fits: Cavenne 2003-2008 Left | 955-341-017-33

Right | 955-341-018-33 List \$364.98 each Sunset \$277.86 each

Watches

911 Sport Classic chronograph Rubber Strap in Silver Grey WAP-070-084-0D

911 Turbo Sport Classic chronograph Rubber Strap in Black WAP-070-083-0D List \$740.00 each Sunset \$586.90 each

Headlight Switch

Fits: Boxster, 996, 996 Turbo, GT3 996-613-535-00 List \$143.89 Sunset \$103.42

We offer our excellent prices on EVERY PORSCHE PART! Call us with your needs.

*All items subject to availability. While supplies last. Price subject to change without notice. All orders will be charged shipping. U.S. only. All orders must be shipping - no "WillCall" orders. Returns must be accompanied by a return authorization number. All orders filled within two weeks unless back ordered from Porsche. Allow apps. two weeks for delivery. USA-Spec. only.

Mention This Ad To Get Your EXCELLENCE Price. SAVE EVEN MORE - NO SALES TAX IN OREGON

Sunset Porsche **Beaverton**, Oregon

1-800-346-0182 Parts Hours M-F 8am-5pm Pacific Time Email: porscheparts@sunsetporsche.com



tech notes

you is a sure recipe for slow times. It's also a good way to make a hexagon out of a circle; instead of driving a smooth arc through a series of cones, you're making a small steering input at each cone and scrubbing speed. Visualize that arc and look ahead 150 feet to that last cone in the sweeper, and you'll gain a tenth of a second or two. Charging into a 180-degree turnaround, your head—and, more importantly, eyes-should be 90 degrees to the direction of travel at your turn-in point, locking in on that exit cone like an F-16's target acquisition system. Last, don't be too hard on yourself and enjoy the experience. It's easy to have high expectations as you improve, which leads to overdriving and toorapid hand motions which kill grip. Be smooth (vet aggressive), look way ahead and be super-tidy around the slowest turns, and you'll be surprised at your times.

Factory Repair Manuals

Do you know if it is possible to access factory repair manuals for 997 series cars? I see Porsche has PIWIS-TIS online for authorized entities including Automobile Clubs. Is there a way I can access this service through PCA? Can you suggest any alternatives? My goal is to start working on my 997 Turbo.

We commend you for trying to obtain the correct information to service and repair your Porsche. Unfortunately, the Porsche PIWIS TSI website is only for "Authorized Companies" and is the only legitimate place we know of to obtain the correct technical information necessary to work on your Porsche. We do not believe that Porsche would agree to a subscription with the Porsche Club of America (PCA) or how it could regulate and control access by PCA's thousands of club members.

Access to the Porsche PIWIS TSI site costs \$5,000 per year plus taxes, and it is specifically intended to be used by automotive repair businesses. The information and materials on the site are writ-

©2013 Porsche Cars North America, Inc. Porsche recommends seat belt usage and observance of all traffic laws at all times.



When carving your niche, use the sharpest instrument available.

This isn't merely the new Porsche Cayman. This is a world unlocked. It's finding enlightenment and exhilaration in those twists in the road. Something we call the Code of the Curve. It's mid-engine balance, agility and precision. Combined with increased horsepower, lighter weight, a wider stance and acceleration from 0 to 60 in a mere 4.7 seconds, it translates into adrenaline-fueled curve-carving that opens up a world of possibilities. Unlock the Code of the Curve with a test drive. Porsche. There is no substitute.

The new Porsche Cayman S.

rsche Dealer

Porsche of Omaha 6625 L Street Omaha, NE 68117 Toll Free: (800) 889-1893 omaha.porschedealer.com mitchs@woodhouse.com



tech notes

ten for the professional mechanic and already assumes the reader has significant experience and training with Porsche cars, plus access to the full complement of specialized Porsche tools referenced in their documentation. Due to the cost for access, many independent Porsche repair shops do not subscribe to this service.

We suggest that you talk to your local professional Porsche repair facility to see if there is a way they can assist you in repairing your car.

Do I Need Spark Plugs?

I own a 2009 Porsche 911 Carrera S Cab. I purchased it new in April 2010, and it currently has 5,800 miles on it. I was told by the dealer that because the car is four years old I need the 40,000-mile service done now—specifically the spark plugs need to be changed. Is this true? If so, can you tell me the reasoning?

Spark plugs are a wear item, and normally their wear is based on miles driven and how those miles were driven rather than from calendar-based time like many liguids are judged. There can be variables in the spark-plug wear equation: the quality of spark plug installed, whether the plugs were gapped correctly, the condition of the ignition coils, plus the type of engine, the mechanical condition of the engine, and the quality of fuel that is being run in the car. Is the car spending a lot of time in slow, heavily congested traffic? Or, at the other extreme, is it constantly being driven flat-out at very high revs, such as on the track? Any of these variables can affect sparkplug life.

On the newer, direct fuelinjected engines such as yours, the spark plugs can be left in for 8-10 years, because fuel delivery is very precise. On previous fuel-injection systems, the cold start and shortdistance driving is best kept to a minimum. Short-distance driving may not allow the spark plugs to be cleaned up or completely recover from the very rich environment of a



A part of the Woodhouse Auto Family



You think it, we can build it. Bisimoto 911 Turbo



simotowerks.com | 1916 S Lynx Place, Ontario, CA 91761 | (888) 922-6686

tech notes

cold-start cycle. Rich running con ditions can coat the spark plug ceramic, and this coating can cause strange operating charac teristics not to mention the possi bility of a misfire, which is the wors scenario on any catalytic con verter-equipped car.

The best action to take is to remove the spark plugs at the vehicle's major service intervals and check the physical condition. If the spark plugs are in good condition they can be reinstalled. Aside from this physical inspection, a drop in fuel mileage can be a key indicator of the need for replacement.

At 5,800 miles we expect you spark plugs will look like new; if so there should be no reason for replacement. We hope you ask th dealer the same question; w would love to know their response

The Right Tire Pressure I have a tire pressure question

continued on page 3



- Multi adjustable short throw shifter
- Billet aluminum
- Adjustable cable mono blocks
- Designed for optional counter weight
- Quick change adjustments on shifter throw 4
- Ball Bearing movement on all rotating axis
- Bulit for racing and longevity. Direct
 replacement in your race or stock car

Main Line: 813-919-9132 Fax: 813-792-2062

dan@numericracing.com www.numericracing.com

그는 승규는 가지 않는 승규는 가지가 많은 것이라. 이 것이라는 것이라는 것이 같은 것이 같이 다니는 것은 것을 수 없을 것을 수 없다.

SUNCOASTPARTS.COM

YOUR ONLINE STORE FOR GENUINE PORSCHE PARTS AND ACCESSORIES

- ACCESSORIES RACING SEATS PADDLE STEERING WHEELS CLEAR SIDE MARKERS SHIFTER KITS
- APPAREL & WATCHES AEROKITS & SPOILERS MARTINI COLLECTION MAINTENANCE PARTS AND MUCH MORE



tech notes

relative to our 2011 Porsche Targa 4. We want the softest ride. The label on the car's door frame shows tire pressures for the front at 37 psi and rear at 44 psi. However, the manual identifies 34/37, respectively. Is it okay to use 34/37 or less than 34/37 to get softest ride?

Some may not know how you obtained the tire pressure information, so we would like to clarify. The correct cold temperature (68°F) tire-pressure inflation levels are listed on the car by government mandate; a tire-pressure plaque is visible when the driver's door is open. In the case of your 2011 C4 Targa, the correct tire pressures are as you identified: 37 psi for the front tires and 44 psi for the rear tires, regardless of whether you have 18- or 19-in. wheels. (Please note that sometimes wheel sizes do impact tire pressures.) This is considered the correct tire pres-




Perfect Partnership For Your Porsche

EXCITING NEWSI

GT Racing is pleased to announce the purchase of European Racing Headers which has an outstanding reputation of crafting performance Porsche header

and exhaust systems for over 40 years!



914.6 Headers



Mandrel Bent 911 RSR Headers Stinger Exhaust with Silencer

High Performance Headers and Exhaust Systems for 911 and 914 Porsche Models



911 RSR Built With GT Racing Panels Parts 35-T11, 16A, 39, 27, 4, 4B, 21 and 26

Quality Light-Weight Porsche Body Panels 911, 914, 944, 968, 951, 993, 996, 997



tech notes

sure for a fully loaded vehicle meaning passengers, luggage and a full tank of fuel.

There should also be a small vellow plague on the door or a notation on the tire-pressure plaque that refers you to the owner's manual for additional tirepressure information. The owner's manual should have the additional information of recommended tire pressures for lighter load conditions, which you have also correctly identified for your model at 34 psi front and 37 psi rear. This would be the minimum tire pressures acceptable for this car. Setting or allowing the tire pressures to operate at lower pressures than those identified could have an extremely negative impact on the life of the tire and the handling of the car

If the inflation is set to a lower level, the rolling resistance of the tires will increase. This in turn will cause a drop in fuel mileage, and the tires will wear significantly faster. According to Porsche documentation, tire wear can be increased by as much as 25 percent if the tire pressure is lowered by as little as 4.5 psi under recommended levels. The tire will lose stability and traction in corning, and steering response will also become sluggish. However, even more importantly, as the rolling resistance increases, the heat generated within the tire also goes up significantly. This type of heat generation can be extremely damaging to the tire's internal structure and has the potential to cause the tire to fail.

You did not mention the tire brand and model currently on the car; however, we assume that it is a Porsche-recommended N-specification tire as delivered from the factory. We suggest that any car under a factory warranty program have N-specification tires installed, as Porsche dealer service department's generally react negatively to tires not on Porsche's approved list—and often with good reason. Having said that, there are new high-performance tires coming into



New from Wossner Pistons...

CHIE 2

Now stocking Porsche 2.0 & 2.4 ltr. piston and cylinder kits.

ORS



PORSCHE

P: 714-369-8879 or 714-369-8547 www.wossnerpistons.com E: sales@wossnerpistons.com

tech notes

the marketplace that can deliver better ride characteristics while providing uncompromising highperformance wet/dry grip, steering response and even much longer tire life than we have seen in the past. Tire design continues to make great strides as improved technology continues to develop better materials and construction methodologies.


993 Valve Guide Problem

I manage a vintage racing prep shop and took the Porsche plunge last week by purchasing a 1998 911 Carrera Cabriolet with 95,000 miles. I wanted a sensible, practical, everyday alternative to the less practical Italian cars I am accustomed to. Porsche reliability has always impressed me, so this car's mileage didn't scare me and its price reflected the mileage quite fairly. I bought the car from the

continued on page 42

ECU or DME?





forged art.

The Fuchs FP.1 Centerlock wheel is the pinnacle of performance wheel design and engineering.

Drop-forged, not roto-forged or cast. FEA optimized for the the ultimate balance between strength and lightweight performance.

Machined with multiple compound curves that are difficult and time consuming, but result in the epitome of beautiful Fuchs design.

The Fuchs FP.1 Centerlock wheel is now available, in standard or fully custom finishes.

For more,please visit fuchsperformance.com or call 949.206.1093





tech notes

second owner, researched the car's history, talked to the original selling dealer, and performed a thorough pre-purchase inspection. Cylinder leakdown was about eight percent in all cylinders except for one, which was 13 percent.

İ thought I'd done my homework, but I ran into a problem when I tried to smog my 993. It passed the tailpipe test but failed due to a trouble code logged in the OBD system indicating a fault in the secondary air-injection system. This really caught me by surprise, as the car showed excellent power and driveability, no Check Engine light indications, and it had normal tailpipe emissions.

Further investigation, however, revealed that the Check Engine indicator lamp had been removed. It promptly illuminated upon installation.

I took the car to our local dealer. The service department confirmed the trouble codes and cleared them, extinguishing the Check Engine light. I was stunned by their diagnosis. They also said this 993 needs valve guides — and that they had seen this problem before.

We build our engines inhouse—from Ferrari V12s to Cosworth DFVs—so I understand engine theory. I cannot fathom how a valve guide problem (assuming one exists) can cause a secondary air-injection system trouble code. When I questioned my service rep about this, the response was that the secondary air-injection system works fine, so it must be the valve guides! I'd very much like a second opinion, and I am happy to pay to have the car inspected again.

The previous owner of the car is willing to take the car back and refund my money, but I really do like this 993 and I feel it's otherwise sound. I spent a lot of time searching for this one and I'm willing to spend a reasonable sum to resolve what I see as an isolated problem. The previous




tech notes

owner is also willing to contribute to any repair costs. I am quite motivated to solve this problem sooner rather than later, given the financial implications.

Sorry to hear that your first experience with Porsche has been an unpleasant one. Clearly, someone has committed fraud by eliminating the check engine light. Someone clearly knew the car had a problem, since the light was circumvented before the car was sold to you. Your cleanest way out probably is to take your money back and look for another car.

The 3.6-liter engines *do* tend to wear their valve guides out—particularly the exhaust-side guides. This wasn't much of a problem until OBD II came along and the secondary air-injection was added to the 1996 993 engines. What happens is that just enough

continued on page 46



GENUINE RUF PARTS AND ACCESSORIES ONLY AT

WWW.RUFAUTO.US

EINMALIG email: einmalig@einmalig.com web: www.einmalig.com

NEW and USED Porsche Parts Minor Tune Ups to Complete Restoration



• Door pockets front and rear with door pulls



 Reconditioned pedal assembly 1965-1983



• 1965-68 911 912 light assemblies reconditioned front and rears with new lenses



• New 911 912 shift knobs 901 and 915 and 930 shift knob

Visit Our New Parts Website www.einmaligparts.com


5455 Production Drive Huntington Beach CA 92649 714.895.6567 ph 714.894.7126 fax 888.777.6772

tech notes

oil gets by the guides to coke up the secondary air-injection ports in the cylinder heads, resulting in the fault you are experiencing.

Porsche started using an airinjection system with the introduction of the 993 in 1995. Unlike earlier air-injection systems-which ran all the timethe purpose of the 993 air-injection setup is to ensure quicker catalytic converter heat-up during cold starts. During cold start (between 59°F and 158°F), a DME-controlled auxiliary air pump blows air into the exhaust ports through passages in the camshaft housing and cylinder heads, which initiates the catalyst "light off" on a cold engine.

The engine management monitors the operation through the voltage values from a single oxygen sensor on early 993s or leftand-right oxygen sensors on later 993s (1996-on) with Motronic 5.2





tech notes

DME with On-Board Diagnostics, Second Generation (OBD II). Normally, the extra air produces an overly lean condition, which causes oxygen-sensor voltage to go down to zero. If there's a problem and voltage is read on either sensor, a fault is read by the DME and the check engine light is illuminated. As you say, you can have this problem and have no driveability problems—the only way you know you have a problem is by the illumination of the CEL.

The problem can have a variety of sources and, unfortunately, the hardest part of diagnosis is access to all of the components involved. Simple repairs would involve air pump seizure or vacuum line problems. The diagnosis and repair can be far more difficult if it involves the internal air passages in the cam housing or the bores to the exhaust ports in the cylinder heads.

Porsche says there is no official repair procedure in this area. Cars

with this issue have been repaired by various means of cleaning out the ports and reopening the air passages. These repairs are often performed only to the blocked side of the engine since both sides are seldom blocked. The blockage usually consists of "coked" oil residue. It is thought that the level of contamination of the motor oil may have an effect on this form of coking and blockage. This may be an argument for more frequent oil changes than the "15,000 miles or once a year" recommendation by Porsche AG.

Most of the cases have occurred in the warmer climates, when the cars also have a lot of city driving. These conditions produce extra heat and can create the right conditions to overheat the engine's oil in this area and then cause the coking. If this happened when the cars were newer or still under warranty, the dealers

